

0233Z 01 NOV 64

S E C R E T

DIRECTOR

25X1A

ROUTINE

TOR: 0257Z 01 NOV 64

IN 55405

OPS 1 - 8

INFO

ONE

5917 25X1A

25X1A

25X1A

A. 0224C

B. 352

C. 25X1A

D. HQ DIRECTED, 3, 26, 8, 30, 33, 34

E. 1. COCKPIT AUTO HEAT CONTROL WILL NOT HOLD A WARM
TEMPERATURE.

2. SYSTEM XIII PRESSURIZATION VALVE CLOSE LIGHT (AMBER)
DID NOT ILLUMINATE WHEN SELECTOR SWITCH WAS PLACED IN CLOSED
POSITION.

END OF MESSAGE